


C.4 RACO VMB-2 Serial Cable Connection Diagram



9 Pin Connector Pin-Out		
2	TXD	Data from Gateway
3	RXD	Data to Gateway
4	DSR	Data Set Ready - Jumpered to DTR at 9 pin conn. only
5	SGND	Signal Ground
6	DTR	Data Terminal Ready - Jumpered to DSR at 9 pin conn. only
7	RTS	Request to Send - Jumpered to CTS at 9 pin conn. only
8	CTS	Clear To Send - Jumpered to RTS at 9 pin conn. only